

00862.022058.



V# Cope
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

TAKUTO HARADA ET AL.

Appln. No.: 09/718,363

Filed: November 24, 2000

For: IMAGE PROCESSING APPARATUS
AND METHOD

U.S. Patent No.: US 6,853,466 B1

Issued: February 8, 2005

)
: Examiner: Tommy D. Lee
)
: Art Unit: 2624
)
:
)
:
)
:
)
:
)
:
)
:
)
:
)

July 7, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JUL 14 2005
of Correction

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.


07/11/2005 SSITHIB1 00000120 6853466
01 FC:1811

100.00 DP

5 700

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Leonard P. Diana
Attorney for Patentees
Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
NY_Main 498536v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,853,466 B1

DATED : February 8, 2005

INVENTOR(S) : TAKUTO HARADA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE [57] ABSTRACT:

Line 15, "ratio," should read --ratios,--.

COLUMN 2:

Line 6, "image:" should read --image;--; and

Line 21, "image:" should read --image;--.

COLUMN 3:

Line 32, "title" should read --tile--; and

Line 34, "in" should be deleted and "sturucture" should read --structure--.

COLUMN 4:

Line 34, "quantized" should read --quantized by--.

COLUMN 5:

Line 56, "in" should read --is--; and

Line 60, "a" should read --as--.

COLUMN 6:

Line 24, "indicates" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,853,466 B1

No. of add'l. copies
@ 30¢ per page



2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,853,466 B1

DATED : February 8, 2005

INVENTOR(S) : TAKUTO HARADA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

Line 31, "c'=0 q=0" should read --c'=0; q=0--.

COLUMN 9:

Line 38, "The" (second occurrence) should read --the--.

COLUMN 11:

Line 9, "The" should read --the--;

Line 60, "indicate" should read --indicates--; and

Line 66, "indicate" should read --indicates--.

COLUMN 12:

Line 4, "indicate" should read --indicates--;

Line 7, "SI a DI" should read --SI α DI--;

Line 16, "indicate" should read --indicates--;

Line 22, "indicate" should read --indicates--; and

Line 28, "indicate" should read --indicates--.

COLUMN 14:

Line 13, "in" should be deleted; and

Line 33, "form" should read --from--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,853,466 B1

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : US 6,853,466 B1

DATED : February 8, 2005

INVENTOR(S) : TAKUTO HARADA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 16, "pint" should read --print--; and

Line 20, "pint" should read --print--.

COLUMN 17:

Line 8, "(type)" should read --(type)--; and

Line 60, "emobdiment." should read --embodiment--.

COLUMN 19:

Line 2, "commanded;" should read --commanded--;

Line 20, "developed" should read --a developed--;

Line 35, "commanded" should read --commanded--; and


Line 45, "a" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,853,466 B1

No. of add'l. copies
@ 30¢ per page



5 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,853,466 B1

DATED : February 8, 2005

INVENTOR(S) : TAKUTO HARADA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 19:

Figure 19, "PATTER" should read --PATTERN--;

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,853,466 B1

No. of add'l. copies
@ 30¢ per page